FEB 1952 31-4MM

no not cirqulate

CENTRAL INTELLIGENCE AGENCY

1. The Progress of Shipbuilding - Type I ships a. The state of completion achieved Patenned Actual		CL	ASSIFICA	ATIC	N SECR	et/(J.S. OFFCIA:	LS ONLY	•				50X1-HU	JM
DOUNTRY East Germany DATE DISTR. 10 October 1952 Side Construction and Repair at Mathias Thesen Werft, Wisman NO. OF PAGES 2 NO. OF ENCLS. SOX1-HUM SUPPLEMENT TO REPORT NO. THIS IS UNEVALUATED INFORMATION THIS IS UNEVALUATED INFORMATION THIS IS UNEVALUATED INFORMATION THE PROGRESS of Shipbuilding - Type I ships à. The state of completion achieved Dockyard No. 10000 13.56 1.0.45 1.1001 The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving the ship was provided with 2200 tons of diesel famil, whereas only 1800 tons had been suthorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOUTERAISIA— This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in the own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SOX1-HUMBERT TORSIA— The stage of Mathias Thesen Werft for a floating crane SOX1-HUMBERT TORSIA— The stage of Mathias Thesen Werft for a floating crane CLASSIFICATION SECRET/CONTROL — U.S. OFFICIALS ONLY						NF	ORMA	T	ION REP	ORT	REPOR	т				
SUBJECT Ship Construction and Repair at Mathias NO. OF ENGLS. SOX1-HUM NO. OF ENGLS. SOX1-HUM NO. OF ENGLS. SOX1-HUM SUPPLEMENT TO REPORT NO. THIS IS UNEVALUATED INFORMATION SOX1-HU Planned Actual Dockyard No. 10000 13.56 10.45 3.56 b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. Refits of Russian ships a. The FOREDA has left for Odessa. Before leaving the ship was provided with 2000 tons of diesel fuel whereas only 1800 tone had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SOC and the Werft. b. KOCPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3) the pressing need of Mathias Thesen Werft for a floating crane CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY						. 1					CD NO) .				
SUBJECT Ship Construction and Repair at Mathias No. OF ENGLS. 50X1-HUM NO. OF ENGLS. 50X1-HUM SUPPLEMENT TO REPORT NO. LACE CQUIRED THIS IS UNEVALUATED INFORMATION 1. The Frogress of Shipbuilding - Type I ships â. The state of completion schieved Dockyard No. 10000 1 3,56 1 0.45 3 b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. 2. Refits of Russian ships a. The POBEDA has left for Odessa. Pefore leaving the ship was provided with 2000 chos of diseafful whoreas only 1800 tone had been authorized by the reparations office. Although 300 tone were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCG and the Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft, has not been in its own vehicle from Leipzig. (3.) the pressing need of Mathias Thesen Werft for a floating crane CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY	COUNTRY	Eas	st German	ny		1.0					DATE I	NETÉ	10.00	tobe	r 1952	: 1
These werft, Wismer ATE OF NO. OF ENCLS. SUPPLEMENT TO REPORT NO. SUPPLEMENT TO REPORT NO. THIS IS UNEVALUATED INFORMATION THIS	•			٠.	ion and	Rer	nair at A	√o+	hies						1 1302	
SUPPLEMENT TO REPORT NO. THE PROGRESS OF SHIPBUILDING TWENTON IN SECTION 19 AND THE WARD STATES AND WARD STATES A	,00001	The	sen Weri	ft,	Wismar	1001	Jul 40 1				NO. OF	PAGES	,	2		
THIS IS UNEVALUATED INFORMATION The Progress of Shipbuilding - Type I ships a. The state of completion achieved Doekyard No. 10000 13.56 1.3.56 1.3.56 1.4.3 b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. 2. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving, the ship was provided with 2200 tons of diesel fuel, whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOFERATSIA- This ship, back at the Methias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY											NO. OF	ENCLS	S. (50X1	-HUM	
THIS IS UNEVALUATED INFORMATION The Progress of Shipbuilding - Type I ships a. The state of completion achieved Dockyard No. 10000													то			1
a. The state of completion achieved Printed Actual	F THE UNITED S ND 794, OF THE ATION OF ITS C	TATES, U.S. (ONTENTS	WITHIN THE ME. CODE, AS AMEND 5 TO OR RECEIP	ANING ED. I T BY A	OF TITLE 18, S TS TRANSMISSI IN UNAUTHORIZE	ECTION ON OR D PERS	IS 793. REVE- SON IS		THIS IS	UNEVAL	.UATED	INFORI	MATION		50X1-HI	UM
a. The state of completion achieved Planned Actual	<u> </u>	The	Progres	a 0	f Shinbu	47.4	ina Tr		Tehin			* 1				
Dockyard No. 10000 13.56 10.45 4.3 b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. 2. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving, the ship was provided with 3200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane 50X1-Hi CLASSIFICATION SECRET/CONTROL - U.S. OFFICIAIS ONLY	- - -										was	as fo	llows:	ı	50 Y 1 HII	IN /I
b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. 2. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving, the ship was provided with 2200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane 50X1-H										•				`	· .	IVI
2. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving the ship was provided with 2200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SECRET/CONTROL - U.S. OFFICIALS ONLY		Ų.						,	13.56 13.56	•				ý.		
a. The POBEDA has left for Odessa. Before leaving the ship was provided with 3200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane 50X1-H		b. main	The rea	son: sh	why thortage o	e pi	lanned caterials	omp ar	oletion stand a lack o	ge was f speci	not rea	ached , part	is exp icular	laine ly w	ed elders.	
reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SOX1-HI CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY	2,	Ref	ts of R	uss:	ian ship	<u>s</u>										
(1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		rope	rations extra v	ofi orl	ice. A had be	ltho en (whereas o ough 300 carried o	on! to out	ly 1,800 ton ons were re- c on the ve	s had b turned, ssel ov	een aut this e er and	thorize event a above	ed by	the		
(2) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3) the pressing need of Mathias Thesen Werft for a floating crane 50X1-HI CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		b. comp	KOOPERAT	ISIA 1 ti	- This a	sh i p is i	o, back a is said t	at to	the Mathia	as Thes t of:	en Werf	t, has	not 1	oeen		
(3.) the pressing need of Mathias Thesen Werft for a floating crane 50X1-H CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		(1	.) the d	lela	yed docl	cine	g of the	νe	ssel;				,		•	
CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		(2) the n in it	ond	elivery wn vehic	of ele	the engi	ne lpz	s which Mai	thias T	hesen W	erft h	ad to	pick	шр	
CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		(3) the p	res	sing nee	eđ c	of Mathia	ເສ	Thesen Werf	t for	a float	ing cr	ane			
SECRET/CONTROL - U.S. OFFICIALS ONLY		S.			4	. :									50X1-HU	JM
STATE X NAVY X NSRB DISTRIBUTION		CL A	SSIFICAT	ΓΙΟΝ	SECRET	r/cc	NTROL -	υ.	S. OFFICIAI	s only						
ARMY X AIR X FBI							DIST	TR I	BUTION							

SE	CCRET/CONTROL - U.S	3. OFFICIALS ONLY		
		2 -		
(4.) the fact borrowed	that workers had from the SCC.	had to use primiting	ve methods,	i.e. pontoons
Under pressure from possible on the KOOP another Object, and on by premium compoints for machines,	ERATSIA. This inc the division of the petitions, into the	cludes the transfer ne present workers, nree shifts. In add	of two welde who are to l lition, the	ers from be spurred issuing ght.
c. MOZHAISKI - Mini has assured the SCC	ster Gerhard Zille that the vessel wi	ill be delivered thi	is year	50X1-HUM Construction
reparation office in the delivery of turb proposed to bring ri in order to do as mu The Mathias Thesen W of floating crane.	ines by Bergmann-E veters employed o ch work as possibl	vill make himself pe Borsig on bridge building Le on her during the	ersonally really in additional to work on the long summer	ition, it is the MOZHAISKI days.
d. IEN-SOVIET - Vertransfer of the KALL be directed to this	NINGRAD (see below	i), all the resulting	ver, in the e	ower would
e. KALININGRAD - Th		for Warnemuer	ide whoma the	50X1-HUM
were removed. This the lack of a floating certain that the removed.	work could not be ng crane. Although	done in the Mathies the KALININGRAD is	Thesen Werf back in Wisman	t because of
the SCC announce	ed that they were	expecting advice fr	om Moscow sh	to cease
to which dock she she work on the KALININGS for immediate transfe	ould enter. The St RAD, but only in s	such measure that th	e vessel wou	ild be ready 50X1-HUM
work on the KALINING for immediate transfer	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM OLOGDA and the 50X1-HUM d to take
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	VORONETS, Vortly, and t	50X1-HUM POLOGDA and the 50X1-HUM and to take 50X1-HUM
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	e VORONETS, Vortly, and to be preparenge this.	50X1-HUM POLOGDA and the 50X1-HUM and to take 50X1-HUM
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	e VORONETS, Vortly, and to be preparenge this.	50X1-HUM POLOGDA and the 50X1-HUM and to take 50X1-HUM
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	e VORONETS, Vortly, and to be preparenge this.	50X1-HUM POLOGDA and the 50X1-HUM and to take 50X1-HUM
work on the KALININGS for immediate transfer f. ZESTRONEZK. If, as a KALININGRAD is transfer.	anticipated, the KG ferred, the Mathia	for repairs are the OPERATSIA leaves sh s Thesen Werft woul	e VORONETS, Vortly, and to be preparenge this.	50X1-HUM POLOGDA and the 50X1-HUM and to take 50X1-HUM

Sanitized Copy Approved for Release 2011/05/09 : CIA-RDP82-00457R014100140001-3 50X1-HUM

Sanitized Copy Approved for Release 2011/05/09 : CIA-RDP82-00457R014100140001-3

SECRET/CONTROL - U.S. OFFICIALS ONLY